National Transportation Safety Board NTSB ID: LAX01LA121 Aircraft Registration Number: N6123A FACTUAL REPORT Occurrence Date: 03/18/2001 Most Critical Injury: Minor AVIATION Occurrence Type: Accident Investigated By: NTSB Location/Time Nearest City/Place State Zip Code Local Time Time Zone 1800 PST OJAI CA 93023 Distance From Landing Facility: Airport Proximity: Off Airport/Airstrip Aircraft Information Summary Aircraft Manufacturer Model/Series Type of Aircraft

Revenue Sightseeing Flight: No

Air Medical Transport Flight: No

Helicopter

Narrative

Schweizer

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On March 18, 2001, about 1800 Pacific standard time, a Schweizer 269C, N6123A, rolled over during a forced landing near Ojai, California. The forced landing was precipitated by a loss of engine power in cruise flight. Sun Air Aviation LLC was operating the helicopter under the provisions of 14 CFR Part 91. The private pilot was not injured and two passengers sustained minor injuries. The helicopter sustained substantial damage. The local personal flight departed Camarillo, California, about 1640. Day visual meteorological conditions prevailed, and no flight plan had been filed. The primary wreckage was at 34 degrees 28.51 minutes north latitude and 119 degrees 23.90 minutes west longitude.

269C

The pilot submitted a written statement. He was in cruise at 4,700 feet. He planned to fly along a ridgeline northwest of Lake Casitas. As he approached the mountaintop, the nose suddenly veered to the left. He heard several coughing sounds from the engine. He entered an autorotation, but could not reach the flat mountaintop. The helicopter collided with the terrain and rolled. He secured the fuel shutoff valve, pulled the mixture control out, and turned the battery and ignition switch off. He observed fuel leaking from the helicopter.

The wreckage was examined by a Safety Board investigator at Ray's Aviation, Santa Paula, California, on May 18, 2001. The investigator established control continuity for the throttle and mixture controls. Both controls moved freely from stop to stop. The bottom spark plugs were removed from each cylinder. The spark plug electrodes were gray in color, which corresponded to normal operation according to the Champion Aviation Check-A-Plug AV-27 Chart.

The Safety Board investigator established continuity for the collective and cyclic. The investigator added 4 quarts of oil and set up a temporary fuel supply. The engine started on the fifth attempt. The engine ran smoothly; oil and fuel pressures indicated within the green operating range on their respective instruments. Once the oil temperature rose into the green operating range, the engine was run up to 2,000 rpm and a magneto check was completed. The rpm dropped about 200 rpm when each magneto was selected, and the engine continued to run smoothly. No fuel or oil leaks were observed after engine shutdown.

An examination of the engine logbooks revealed that maintenance personnel complied with TEXTRON Lycoming Mandatory Service Bulletin 388B on February 16, 2001, at a Hobbs time of 409.6 hours. This inspection revealed that the exhaust guides for cylinders No. 3 and No. 4 were not within the allowable limit range. The exhaust pushrods for both cylinders were damaged and replaced. Maintenance personnel reamed the exhaust guides in both cylinders as corrective action. The Hobbs meter read 462.6 at the examination. The accident occurred at an estimated 230 hours since the engine was overhauled by a maintenance facility.

On June 15, 2001, a Safety Board investigator and the Textron Lycoming representative removed and disassembled all four cylinders. They determined the pushrods were straight. The exhaust valve

National Transportation Safety Board
FACTUAL REPORT

AVIATION

NTSB ID: LAX01LA121

Occurrence Date: 03/18/2001

Occurrence Type: Accident

Narrative (Continued)

for cylinder No. 4 appeared different from the other exhaust valves. The number 4 piston was not mechanically damaged. Cylinder No.4 was sent to the Lycoming factory.

The No. 4 cylinder exhaust valve was inspected under the supervision of a Safety Board investigator at the Textron Lycoming facility in Williamsport, Pennsylvania, on September 20, 2001. An oversized "go-no go" tool was used to examine the exhaust guide of the cylinder, with no discrepancies noted. The exhaust valve stem was inspected under a microscope and no metal transfer was observed on the stem.

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: LAX01LA121

Occurrence Date: 03/18/2001

AVIATION Occurre			rence Typ	pe: A	ccident	1								
Landing Facility/Approach In	formation						•							
Airport Name		,	Airport ID:	: /	Airport Elevation Ft. MSL		nway Used	Runwa	y Length	n I	Runwa	ay Width		
Runway Surface Type: Unknown								'						
Runway Surface Condition: Unkno	own													
Approach/Arrival Flown: NONE	<u> </u>													
VFR Approach/Landing: Forced L	anding													
Aircraft Information														
Aircraft Manufacturer Schweizer			Mod 269	del/Se 9C	eries				Serial I S152	ial Number 523				
Airworthiness Certificate(s): Norm	al		!											
Landing Gear Type: Skid														
1				fied N	Max Gross Wt.		2050 LBS Numbe			er of Engines: 1				
			_	Engine Manufacturer: Model/Series: Lycoming HIO-360-D1A						Rated Power: 170 HP				
- Aircraft Inspection Information							•			•				
Type of Last Inspection Dat				Date of Last Inspection			Time Since Last Inspection					Airframe Total Time		
100 Hour 03				03/2001			37 Hours				32	94 Hours		
- Emergency Locator Transmitter (ELT) Information								-					
ELT Installed?/Type Yes /			ELT Ope	LT Operated? Yes ELT Aided in Locating Accident Site?										
Owner/Operator Information														
Registered Aircraft Owner			Stree	et Ado	dress									
SUN AIR AVIATION LLC			City									Zip Code		
				CAMARILLO Street Address								93010		
Operator of Aircraft			Street	i Add	ress									
-				City							- 1	Zip Code		
Operator Does Business As:				CAMARILLO CA Operator Designator Code:								93010		
- Type of U.S. Certificate(s) Held: 1	None						perator Design	nator oc	ue.					
Air Carrier Operating Certificate(s)														
Operating Certificate:					Operator Certific	cate:								
Regulation Flight Conducted Unde	r: Part 91: Genera	ıl Aviati	on											
Type of Flight Operation Conducted	d: Personal													
		FACTU	JAL REF	POR	Γ - AVIATION							Page 2		

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: LAX01LA121

Occurrence Date: 03/18/2001

AVIATION				Occurrence Type: Accident										
First Pilot	Information													
Name City											State	; D	ate of Birth	Age
On File						On Fi	n File				On F	ile (On File	24
Sex: M	own				Cert	tificate	Numbe	r: On File	•					
Certificate(s): Priva	ate								•				
Airplane Rating(s): None														
Rotorcraft/Glider/LTA: Helicopter														
Instrument	Rating(s): None	<u> </u>												
Instructor R	Rating(s): None	е												
Current Bie	nnial Flight Revie	ew? 12/2000)											
Medical Ce	rt.: Class 2	Medica	al Cert. Status	s: Valid Med	dicalno wa	aivers/l	lim.		D	ate of La	st Med	dical Ex	am: 08/200	0
		· ·												
- Flight Tim	ne Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Nig	Night Instru		Instrument Simulated		R	otorcraft	Glider	Lighter Than Air
Total Time	Total Time 109		80	25		12					1	86	3	
Pilot In Con	nmand(PIC)	and(PIC) 29 21							\perp	21				
Instructor						_					_		-	
Instruction		40	40	0.4							\perp	4.0		
Last 90 Day		43 28	16 4	24 14			8			1		18		
Last 30 Day		20		17		+			\dashv		+	- 10	' 	
Seatbelt Us	-	Shou	lder Harness	Used? Yes			Toxicology Performed? No Second Pi					ond Pilot? N	10 	
Flight Pla	n/Itinerary													
	ght Plan Filed: No	one												
Departure F	Point						State Airp		Airport Identifier		r	Departure Time		Time Zone
CAMARILLO									СМА			1640		PST
Destination State Airport Identifier														
Local Flight														
Type of Clearance: None														
Type of Airspace: Class G														
Weather Information														
Source of Wx Information:														
	Unkno	wn												
				FACTUAL	REPORT	- AVI	ATION	1						Page 3

National Transportation Safety Board
FACTUAL REPORT

NTSB ID: LAX01LA121

Occurrence Date: 03/18/2001

AVIATION			Occurre	Occurrence Type: Accident									
Weather Information													
WOF ID	Observation Time	Time Zone	WOF Elevation WOF Distance From Accid				m Accid	dent Site	ent Site Direction From Accide			Site	
SBA	1753	PST	10 F	t. MSL					24 NM		240 Deg. Mag.		
Sky/Lowes	t Cloud Condition: Few				15	15000 Ft. AGL		Condition of Light: Day					
Lowest Cei	iling: None		F	t. AGL	Visib	lity:	10	SM	Alti	meter:	30.06	"Hg	
Temperatu	ıre: 16 °C [Dew Point:	14 °C	Weat	her Condi	tions at Acc	cident S	ite: Visual (Cond	ditions			
Wind Direc	ction: 250	Wind Speed:	5		Wind	d Gusts:							
Visibility (R	RVR): Ft.	Visibility (RV	V)	SM									
Precip and	l/or Obscuration:												
Accident	Accident Information												
Aircraft Damage: Substantial				Aircraft Fire: None				Aircraft Explosion None					
- Injury Sur	mmary Matrix	Fatal Seri	ous Mi	nor	None	TOTAL							
First Pil	lot				1	1	ī						
Second	d Pilot						1						
Student	t Pilot						1						
Flight Ir	nstructor						1						
Check F	Pilot						1						
Flight E	ngineer						7						
Cabin A	Attendants						7						
Other C	Crew						7						
Passen	igers			2		2	2						
- TOTAL A	ABOARD -			2	1	3	7						
Other G	Ground						1						
- GRAND	TOTAL -			2	1	3	3						

National Transportation Safety Board

FACTUAL REPORT AVIATION

NTSB ID: LAX01LA121

Occurrence Date: 03/18/2001

Occurrence Type: Accident

A I				
Δdn	niniet	rativa	Intor	mation
Aun	11111131	Iauve	HILL	manor

Investigator-In-Charge (IIC)

HOWARD D. PLAGENS

Additional Persons Participating in This Accident/Incident Investigation:

DON WARNER Federal Aviation Administration Van Nuys, CA

MARK PLATT Textron Lycoming Van Nuys, CA

Henry Gantner Sun Air Aviation LLC Camarillo, CA